

Photo#1:  
Overview of Location from West to East.



January 8, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: TEP Clough Loc#335179


Photo#2:

View West along South edge of Location.



Photo#3:

View Northeast from Pad edge over large Interim Reclamation area.



January 8, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: TEP Clough Loc#335179



Photo#4:

Aerial view COGCC Maps 2009. It needs to be determined if the whole of the Disturbed area (approximately 2.5 Acres to the North of Location) is part of the Interim Reclamation for Subject Location or is Related / Associated with other Facility.



January 8, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: TEP Clough Loc#335179