

Inspection Photos

API: 05-067-09137

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602417

Inspection Date: 1/4/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 3. View of the western portion of the project area from northwestern corner facing southward. Revegetation is progressing and largely comprised of intermediate wheatgrass (*Thinopyron intermedium*) and western wheatgrass (*Pascopyrum smithii*).



Photo 4. View of Canada thistles (*Cirsium arvense*) within the northeastern portion of the project area.



Photo 5. View of erosional channels approximate 1.5 feet wide and deep in the northeastern portion of the project area.



Photo 6. View of musk thistles (*Carduus nutans*) and sign debris within the southern portion of the project area.



Photo 7. View of erosional channels at the entrance to the well pad.