

Inspection Photos

API: 05-067-06556

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602419

Inspection Date: 1/4/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 3. View of the eastern portion of the project area from southeastern corner facing northward. Revegetation is progressing and largely comprised of dropseed (*Sporobolus* sp.), intermediate wheatgrass (*Thinopyron intermedium*) and western wheatgrass (*Pascopyrum smithii*).





Photo 4. View of wood and pipe debris in the southern portion of the project area.