

Inspection Photos

Location Name: **FEDERAL 1-30**

API: 05-103-08096



Battery sign – missing nearest public access road & emergency contact



Well

Inspection Photos

Location Name: **FEDERAL 1-30**

API: 05-103-08096



Weeds/Brush around equipment



Weeds/Brush around equipment

Inspection Photos

Location Name: **FEDERAL 1-30**

API: 05-103-08096



Weeds/Brush around equipment



Crude oil tank label



Inspection Photos

Location Name: **FEDERAL 1-30**

API: 05-103-08096



Production water tank label



Bird protector – not able to determine if present.

Inspection Photos

Location Name: **FEDERAL 1-30**

API: 05-103-08096



Weeds/Brush in blow down pit



Weeds/Brush in blow down pit



Inspection Photos

Location Name: **FEDERAL 1-30**

API: 05-103-08096



Weeds/Brush in blow down pit



Erosion cuts into blow down pit

Inspection Photos

Location Name: **FEDERAL 1-30**

API: 05-103-08096



Erosion cuts into blow down pit



Erosion cuts into blow down pit

Inspection Photos

Location Name: **FEDERAL 1-30**

API: 05-103-08096



Erosion cuts into blow down pit



Erosion cuts into blow down pit



Inspection Photos

Location Name: **FEDERAL 1-30**

API: 05-103-08096



Erosion cuts into blow down pit



Slope not stable – erosion cuts