

Inspection Photos
Location Name: Musser, B W "A" 1
API: 05-081-05453



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. No capacity on tank label.