

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2018

Submitted Date:

01/16/2018

Document Number:

680302886**FIELD INSPECTION FORM**

Loc ID 421361 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Operator Information:**OGCC Operator Number: 200149Name of Operator: ATLAS RESOURCES LLC DBA ATLAS ROCKIES LLCAddress: 3500 MASSILLON ROAD #100City: UNIONTOWN State: OH Zip: 44685**Findings:**3 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Walker, Chris	(817)439-4561	cwalker@atlasenergy.com	<a href="#">All Inspections</a>
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421363	WELL	PR	02/27/2012	GW	095-06306	Enninga 943-21-23	SI

**General Comment:**[Routine Site Inspection FIR](#)[Contact: COGCC Engineering Supervisor \(Diana Burn\) for directives.](#)[Enforcement Supervisor \(Jeremy Ferrin\) for directives.](#)[Quality Assurance Supervisor \(Mike Leonard\) for directives.](#)

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:	Install sign to comply with Rule 210 series.	Date:	02/10/2018

**Emergency Contact Number:**

Comment:		
Corrective Action:	Install sign to comply with Rule 210 series.	Date: 02/10/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 421363 Type: WELL API Number: 095-06306 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Well is SI/TA. Last production report June 2017.Corrective Action: Update well status. Update production report. Install valid signage. Date: 02/10/2018