

# Construction and Stormwater Inspection

January 12, 2018

Operator: PDC ENERGY INC - #69175

Location ID: 449952

Inspection Document #: 682403203

Weld County, CO

NWNW Section 11 T5N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Fern /5N65W11EJ  
Location ID: 449952



**Photo 1.** Photo taken from the entrance of location, facing West. Vehicle tracking device installed with road base.



**Photo 2.** Photo taken from the entrance of location, facing North. Operator IN-PROCESS of constructing what appears to be a sediment trap.

Inspection Photos  
Location Name: Fern /5N65W11EJ  
Location ID: 449952



**Photo 3.** Photo taken from the northwestern location, facing East. Ditch and berm BMP installed.



**Photo 4.** Photo taken from the northeastern location, facing South. See comments under Photo 2.

Inspection Photos  
Location Name: Fern /5N65W11EJ  
Location ID: 449952



**Photo 5.** Photo taken from the northeastern location, facing South. See comments under Photo 3.



**Photo 6.** Photo taken from the eastern location, facing West. Operator IN-PROCESS of constructing what appears to be a retention area.

Inspection Photos  
Location Name: Fern /5N65W11EJ  
Location ID: 449952



**Photo 7.** Photo taken from the eastern location, facing West. See comments under Photo 2.



**Photo 8.** Photo taken from the southeast location, facing West. See comments under Photo 2.

Inspection Photos  
Location Name: Fern /5N65W11EJ  
Location ID: 449952



**Photo 9.** Photo taken from the southwest location, facing West. See comments under Photo 6.



**Photo 10.** Photo taken from the southwest location, facing North. See comments under Photo 3.