

# Inspection Photos

API: 05-067-06543

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602425

Inspection Date: 1/9/2018



**Photo 1. View of the project area from the northeastern corner facing center.**





**Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.**





**Photo 3. View of the eastern portion of the project area from northeastern corner facing southward. Revegetation is progressing, largely with grasses such as smooth brome (*Bromus inermis*) and western wheatgrass (*Pascopyrum smithii*).**