

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/18/2018

Submitted Date:

01/18/2018

Document Number:

679903820**FIELD INSPECTION FORM**Loc ID 321840 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 61250Name of Operator: MULL DRILLING COMPANY INCAddress: 1700 N WATERFRONT PKWY B#1200City: WICHITA State: KS Zip: 67206-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Smalley, Carl	719-767-8805	csmalley@mulldrilling.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208186	WELL	SI	10/01/2017	OW	017-07121	NW ARAPAHOE UT (NWAU) 4	PR

**General Comment:**[Routine Inspection](#)

## Location

<b>Lease Road:</b>			
Type	Access		
comment:	Elevated gravel road through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs by tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Metal panels around ECD		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:	Treater on north side of vertical treater		
Corrective Action:		Date:	

Type: Flare	# 0		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 0		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	East side of location		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Electric panel, cathodic rectifier, elec transfer pump in metal shed by water tank, chemical drum in metal shed with VGS		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator in metal shed on northeast side of location		
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Lufkin 320		
Corrective Action:			Date:
Type: LACT	# 0		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		38.901960,-102.183830
Comment:	Water tank is on south side of oil tanks				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		Shared berms					
Corrective Action:							Date:
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	3	400 BBLs	STEEL AST		38.901960,-102.183830		
Comment:							
Corrective Action:							Date:
<b>Paint</b>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:							Date:
<b>Venting:</b>							
Yes/No	NO						
Comment:							
Corrective Action:							Date:
<b>Flaring:</b>							
Type	Ignitor/Combustor						
Comment:	Pilot is lit on ECD						
Corrective Action:							Date:

Inspected Facilities									
Facility ID:	208186	Type:	WELL	API Number:	017-07121	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central tank battery for (NWAU 2, 3, 4, 5, 6 & 38) 790' W @ 38.901960/-102.183830								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT