

Inspection Photos

Location Name: Wickstrom 6 Central Tank Battery

Location ID 435380

Inspection Date: 1/18/2018



Photo 1 -View of impacted rangeland south of heater treater



Photo 2 – View of impacted rangeland looking southeast of heater treater



Inspection Photos

Location Name: Wickstrom 6 Central Tank Battery

Location ID 435380

Inspection Date: 1/18/2018



Photo 3 – View of impacted rangeland looking north at heater treater

-

