

Inspection Photos  
Location Name: Cow Skull 11-89-18 1  
Location ID: 414132



**Photo 1. Pipe and pump jack parts still stored on location.**



**Photo 2. Pump jack disconnected from well.**

Inspection Photos  
Location Name: Cow Skull 11-89-18 1  
Location ID: 414132



Photo 3. Chemical container not connected to well.



Photo 4. Empty chemical container next to pump jack.

Inspection Photos  
Location Name: Cow Skull 11-89-18 1  
Location ID: 414132



**Photo 5. New signs and capacity have been added to produced water tanks.**