

# Interim Reclamation and Stormwater Inspection

January 12, 2018

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 438730

Inspection Document #: 682403207

Weld County, CO

NENE Section 32 T5N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: State Pronghorn /V-32 Pad  
Location ID: 438730



**Photo 1.** Photo taken from the eastern location , facing South. Photo indicates unmanaged Russian thistle (*Salsola tragus*-tumbleweed) throughout the perimeter and interim areas which is considered weed debris.



**Photo 2.** Photo taken from the eastern location, facing East. Sediment trap in need of maintenance- sediment accumulation.

Inspection Photos  
Location Name: State Pronghorn /V-32 Pad  
Location ID: 438730



**Photo 3.** Photo taken from the southeastern location, facing South. Photo indicates unmanaged weed debris.



**Photo 4.** Photo taken from the southeastern location, facing West. See comments under Photo 3.



Inspection Photos  
Location Name: State Pronghorn /V-32 Pad  
Location ID: 438730



**Photo 5.** Photo taken from the southeastern perimeter of location, facing West. Interim areas are not reflective of reference area vegetative levels.



**Photo 6.** Photo taken from the western location, facing North. See comments under Photo 3.