

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2018

Submitted Date:

01/19/2018

Document Number:

689500535**FIELD INSPECTION FORM**Loc ID 336007 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 600 E EXCHANGE AVECity: FORTH WORTH State: TX Zip: 76164**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:21 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	Piceance Creek insp
Dooling, Jessica		Jessica_Dooling@xtoenergy.com	Piceance Creek insp

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299793	WELL	PR	06/01/2013	GW	103-11420	FREEDOM UNIT 197-33B7	PR
299794	WELL	PR	06/01/2013	GW	103-11421	FREEDOM UNIT 197-33B8	PR
299795	WELL	PR	06/01/2013	GW	103-11422	FREEDOM UNIT 197-33B9	PR
299796	WELL	PR	06/01/2013	GW	103-11423	FREEDOM UNIT 197-33B10	PR
299797	WELL	PR	06/01/2013	GW	103-11424	FREEDOM UNIT 197-33B6	PR
299798	WELL	PR	06/01/2013	GW	103-11425	FREEDOM UNIT 197-33B5	PR
299799	WELL	PR	06/01/2013	GW	103-11426	FREEDOM UNIT 197-33B4	PR
299800	WELL	PR	06/01/2013	GW	103-11427	FREEDOM UNIT 197-33B2	SI
299801	WELL	PR	01/01/2017	GW	103-11428	FREEDOM UNIT 197-33B1	PR
300296	WELL	PR	06/01/2013	GW	103-11433	FREEDOM UNIT 197-33B3	PR

General Comment:On location to conduct routine inspection

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-675-4117

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Telecom/solar station		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	Separator/gas meter skid unit for entire location		
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		

Comment:	Chem tote with secondary containment		
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	299793	Type:	WELL	API Number:	103-11420	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR - via plunger lift - no leaks/venting								
Corrective Action:						Date:			
Facility ID:	299794	Type:	WELL	API Number:	103-11421	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR - via plunger lift - no leaks/venting								
Corrective Action:						Date:			
Facility ID:	299795	Type:	WELL	API Number:	103-11422	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR - via plunger lift - no leaks/venting								
Corrective Action:						Date:			
Facility ID:	299796	Type:	WELL	API Number:	103-11423	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR - via plunger lift - no leaks/venting								
Corrective Action:						Date:			
Facility ID:	299797	Type:	WELL	API Number:	103-11424	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR - via plunger lift - no leaks/venting								
Corrective Action:						Date:			
Facility ID:	299798	Type:	WELL	API Number:	103-11425	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR - via plunger lift - no leaks/venting								
Corrective Action:						Date:			
Facility ID:	299799	Type:	WELL	API Number:	103-11426	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR - via plunger lift - no leaks/venting								
Corrective Action:						Date:			
Facility ID:	299800	Type:	WELL	API Number:	103-11427	Status:	PR	Insp. Status:	SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: [SI - no leaks/venting](#)

Corrective Action:

Date:

Facility ID: 299801 Type: WELL API Number: 103-11428 Status: PR Insp. Status: PR

Producing WellComment: [PR - via plunger lift - no leaks/venting](#)

Corrective Action:

Date:

Facility ID: 300296 Type: WELL API Number: 103-11433 Status: PR Insp. Status: PR

Producing WellComment: [PR - via plunger lift - no leaks/venting](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass					
Compaction	Pass					
Ditches	Pass					

Comment: [No sediment flow evident](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689500536	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4356419