

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2018

Submitted Date:

01/19/2018

Document Number:

689500539**FIELD INSPECTION FORM**Loc ID 336018 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 600 E EXCHANGE AVECity: FORTH WORTH State: TX Zip: 76164**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:20 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica		Jessica_Dooling@xtoenergy.com	Piceance Creek insp
Reid, Van		van_reid@xtoenergy.com	Piceance Creek insp

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293172	WELL	SI	09/01/2017	GW	103-11097	FREEDOM UNIT 197-33A3	PR
293173	WELL	PR	06/01/2015	GW	103-11101	FREEDOM UNIT 197-33A5	PR
293174	WELL	PR	06/01/2013	GW	103-11100	FREEDOM UNIT 197-33A4	PR
293176	WELL	PR	06/01/2013	GW	103-11099	FREEDOM UNIT 197-33A1	PR
293178	WELL	PR	04/01/2017	GW	103-11098	FREEDOM UNIT 197-33A2	SI
299330	WELL	PR	03/01/2017	GW	103-11399	FREEDOM UNIT 197-33A7	PR
299331	WELL	PR	03/01/2017	OW	103-11400	FREEDOM UNIT 197-33A9	PR
299332	WELL	PR	03/01/2017	GW	103-11401	FREEDOM UNIT 197-33A8	PR
412690	WELL	PR	03/01/2017	GW	103-11535	FREEDOM UNIT 197-33A6	PR

General Comment:On location to conduct routine inspection

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-675-4117

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Telecom/solar charge shed		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chem tote with secondary containment		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	Separator/gas meter skid unit for entire location		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

PRODUCED WATER	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities				
Facility ID: 293172	Type: WELL	API Number: 103-11097	Status: SI	Insp. Status: PR
Producing Well				
Comment: PR - via plunger lift, no leaks/venting				
Corrective Action:		Date:		
Facility ID: 293173	Type: WELL	API Number: 103-11101	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR - via plunger lift, no leaks/venting				
Corrective Action:		Date:		
Facility ID: 293174	Type: WELL	API Number: 103-11100	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR - via plunger lift, no leaks/venting				
Corrective Action:		Date:		
Facility ID: 293176	Type: WELL	API Number: 103-11099	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR - via plunger lift, no leaks/venting				
Corrective Action:		Date:		
Facility ID: 293178	Type: WELL	API Number: 103-11098	Status: PR	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: EQUIPMENT ONSITE				
Comment: SI - no leaks/venting				
Corrective Action:		Date:		
Facility ID: 299330	Type: WELL	API Number: 103-11399	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR - via plunger lift, no leaks/venting				
Corrective Action:		Date:		
Facility ID: 299331	Type: WELL	API Number: 103-11400	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR - via plunger lift, no leaks/venting				
Corrective Action:		Date:		
Facility ID: 299332	Type: WELL	API Number: 103-11401	Status: PR	Insp. Status: PR

Producing Well			
Comment:	PR - via plunger lift, no leaks/venting		
Corrective Action:		Date:	
Facility ID:	412690	Type:	WELL
API Number:	103-11535	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	PR - via plunger lift, no leaks/venting		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Compaction	Pass					
Gravel	Pass					
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689500540	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4356421