

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401520769

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>HOMESTEAD OIL INC</u>	Operator No: <u>41050</u>	Phone Numbers
Address: <u>16880 WILD PLUM CIRCLE</u>		Phone: <u>(303) 829-3176</u>
City: <u>MORRISON</u>	State: <u>CO</u>	Zip: <u>80465</u>
Contact Person: <u>Phil Wright</u>	Email: <u>philwrightdenver@gmail.com</u>	Mobile: <u>()</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 8307Initial Form 27 Document #: 2148351

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input checked="" type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input checked="" type="checkbox"/> Other <u>TANK BATTERY</u> |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>LOCATION</u>	Facility ID: <u>319606</u>	API #: <u></u>	County Name: <u>WELD</u>
Facility Name: <u>STEPHENS-64N66W 15SWNW</u>	Latitude: <u>40.314245</u>	Longitude: <u>-104.769741</u>	
** correct Lat/Long if needed: Latitude: <u></u>		Longitude: <u></u>	
QtrQtr: <u>SWNW</u>	Sec: <u>15</u>	Twp: <u>4N</u>	Range: <u>66W</u>
Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>		

SITE CONDITIONS

General soil type - USCS Classifications SPMost Sensitive Adjacent Land Use CROP LANDIs domestic water well within 1/4 mile? YesIs surface water within 1/4 mile? YesIs groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

SITE INVESTIGATION PLAN

TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☐ Produced Water

☐ Workover Fluids

☐ Oil

☐ Tank Bottoms

☒ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	20 Ft x 60 Ft	Installed 8 monitoring wells
Yes	SOILS	8 ft x 8 ft	VISUAL

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

REFER TO PREVIOUSLY FILLED FORM 19 FOR SAME API NUMBER (SPILL #2148350). Facility was abandoned after P&A of well.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Refer to Site Investigation Report dated 9/1/14. Eight soil samples were collected via soil borings.

Proposed Groundwater Sampling

☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Refer to Site Investigation Report dated 9/1/14. Eight monitoring wells were installed and have been sampled approximately on a quarterly basis.

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 8

Number of soil samples exceeding 910-1 1

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 64

NA / ND

-- Highest concentration of TPH (mg/kg) 1618

NA Highest concentration of SAR

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 16

Groundwater

Number of groundwater samples collected 8

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet) 20'

Number of groundwater monitoring wells installed 8

Number of groundwater samples exceeding 910-1 2

-- Highest concentration of Benzene (µg/l) 2616

-- Highest concentration of Toluene (µg/l) 3751

-- Highest concentration of Ethylbenzene (µg/l) 4182

-- Highest concentration of Xylene (µg/l) 96434

NA Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Impacted soil removed via excavator and trucks. Residual ground water impacts removed via air sparging and soil vapor extraction.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Since the soil consists of mostly sand, air sparging and soil vapor extraction (AS/SVE) was an effective remedial technology. Nine AS and four SVE wells were installed at the site to remediate residual impacts.

Soil Remediation Summary

☒ In Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

Yes _____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

☐ Ex Situ

Yes _____ Excavate and offsite disposal

_____ If Yes: Estimated Volume (Cubic Yards) _____ 120

_____ Name of Licensed Disposal Facility or COGCC Facility ID # _____

_____ Excavate and onsite remediation

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

☐ _____ Bioremediation (or enhanced bioremediation)

☐ _____ Chemical oxidation

Yes _____ Air sparge / Soil vapor extraction

☐ _____ Natural Attenuation

☐ _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Refer to Site Investigation Report dated 9/1/14 and Ground Water Data and Closure Submittal dated 1/20/18. Eight monitoring wells have been used to monitor ground water remediation progress. These wells have now had four consecutive quarters of COGCC-compliant BTEX concentrations.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☒ Quarterly ☐ Semi-Annually ☐ Annually ☐ Other _____

Report Type: ☒ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report

☐ Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

None

Volume of E&P Waste (solid) in cubic yards 120

E&P waste (solid) description Condensate impacted soil

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: Waste Management Buffalo Ridge Landfill

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description None

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes

Do all soils meet Table 910-1 standards? Yes

Does the previous reply indicate consideration of background concentrations? Yes

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? Yes

Does Groundwater meet Table 910-1 standards? Yes

Is additional groundwater monitoring to be conducted? No

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

ALL EQUIPMENT REMOVED FROM TANK BATTERY SITE. SITE IS ~10 YDS X 30 YDS. SITE IS VERY LEVEL. COMPACTION AFTER WORK BY HEAVY EQUIPMENT. SEEDING WILL BE BY FARMER OR AS DIRECTED BY FARMER. LIKELY WILL BE WINTER WHEAT.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☒ Final?

Did the Surface Owner approve the seed mix? Yes

If NO, does the seed mix comply with local soil conservation district recommendations? Yes

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 03/24/2014

Actual Spill or Release date, if known. 03/24/2014

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 03/24/2014

Date of commencement of Site Investigation. 03/24/2014

Date of completion of Site Investigation. 09/01/2014

REMEDIAL ACTION DATES

Date of commencement of Remediation. 05/01/2014

Date of completion of Remediation. 01/12/2018

SITE RECLAMATION DATES

Date of commencement of Reclamation. 04/01/2018

Date of completion of Reclamation. 04/01/2018

OPERATOR COMMENT

Homestead Oil Inc. requests Closure of this site since there have been four consecutive COGCC-compliant ground water sampling events.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Paul Henehan

Title: Engineer

Submit Date:

Email: paulh@fremontenv.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:

Date:

Remediation Project Number: 8307

COA Type

Description

--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

401520782	REMEDIAL ACTION PLAN
401520786	MONITORING REPORT
401520788	SITE INVESTIGATION REPORT

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)