

Photo#1:  
View North over Location Center



Photo#2:  
View South over Location Center



January 9, 2018

Photo#3:  
View East over Location Center



Photo#4:  
View West over Location Center



January 9, 2018

Photo#5:

Close up of well established Vegetation.



January 9, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Encana PA KRK API#045-07306