



Form Information


Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jan 12, 2018 4:12:14 PM MST
Server Receive Date:	Jan 12, 2018 4:12:19 PM MST
Reference Number:	20180112-1871759494
Location:	101-1079 S Skylane Dr, Durango, CO 81303, USA Jan 12, 2018 4:12:10 PM MST [View Map]

Information


Name	reclamationtablet
Date	Jan 9, 2018
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	NE Team
Well Name	GOSNEY GAS COM A 2
API Number	50670880900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Land Owner Debris
Picture North to South	



Picture South to North



Picture East to West



Completed work description

Notes

cut and removed weed debris

site includes gosney gas com a3 and a4