



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Jan 22, 2018 7:32:46 AM MST
Server Receive Date:	Jan 22, 2018 7:33:27 AM MST
Reference Number:	20180122-1872097939
Location:	3601 N 1st St, Bloomfield, NM 87413, United States
	Jan 22, 2018 7:32:40 AM MST [View Map]

Information

Name	celkins@gobrainstorm.net
Date	Jan 17, 2018
Well Name	FRENCH GAS UNIT 01-09U FT 2R
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Contaminated Soils Removed sediment from BMP's

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos

