



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Jan 16, 2018 3:26:27 PM MST
Server Receive Date:	Jan 22, 2018 7:33:24 AM MST
Reference Number:	20180122-1872097934
Location:	Durango, CO 81303, United States
	Jan 16, 2018 3:24:59 PM MST [View Map]

Information

Name	celkins@gobrainstorm.net
Date	Jan 16, 2018
Well Name	BLACK GAS UNIT 21-22 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean up Operator Debris Clean Up Contaminated Soils

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos

