



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Clay Elkins (celkins@gobrainstorm.net)
Submission Date: Jan 22, 2018 7:45:56 AM MST
Server Receive Date: Jan 22, 2018 7:46:10 AM MST
Reference Number: 20180122-1872102195
Location: 3601 N 1st St, Bloomfield, NM 87413, United States
Jan 22, 2018 7:45:52 AM MST [[View Map](#)]

Information

Name	celkins@gobrainstorm.net
Date	Jan 18, 2018
Well Name	MAYFIELD GAS UNIT B 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Land Owner Debris Clean Up Contaminated Soils

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos

