



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jan 4, 2018 3:23:06 PM MST
Server Receive Date:	Jan 4, 2018 3:23:14 PM MST
Reference Number:	20180104-1871406960
Location:	784 Co Rd 520, Bayfield, CO 81122, USA Jan 4, 2018 3:22:58 PM MST [View Map]

Information


Name	reclamationtablet
Date	Jan 4, 2018
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	NE
Well Name	COUCH GAS UNIT 1-16U 3
API Number	50670932500
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos



Completed work description

removed musk thistle skeletons and rosettes