

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/18/2018

Submitted Date:

01/18/2018

Document Number:

689700894**FIELD INSPECTION FORM**Loc ID 335656 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278559	WELL	PR	12/05/2006	GW	045-10895	N.PARACHUTE WF16D O23 596	PR
278560	WELL	PR	08/01/2010	GW	045-10894	N. PARACHUTE WF16B O23 596	PR
278561	WELL	SI	05/01/2017	GW	045-10893	N.PARACHUTE WF13D O23 596	SI
278563	WELL	PR	06/28/2005	GW	045-10892	N.PARACHUTE WF13B O23 596	PR
278568	WELL	PR	06/23/2006	GW	045-10891	N.PARACHUTE WF12B O23 596	PR
278572	WELL	PR	06/03/2006	GW	045-10890	N.PARACHUTE WF10D O23 596	PR
278575	WELL	PR	06/04/2006	GW	045-10889	N.PARACHUTE WF09D O23 596	PR
278577	WELL	PR	02/01/2014	GW	045-10888	N.PARACHUTE WF04B O23 596	PR

General Comment:

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 8		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical container at meters.		
Corrective Action:		Date:	

Type: Gas Meter Run	# 10	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type		
Comment:		
Corrective Action:		
		Date:

Inspected Facilities									
Facility ID:	278559	Type:	WELL	API Number:	045-10895	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	278560	Type:	WELL	API Number:	045-10894	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	278561	Type:	WELL	API Number:	045-10893	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____								
Comment:	Well is shut in.								
Corrective Action:						Date:			
Facility ID:	278563	Type:	WELL	API Number:	045-10892	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	278568	Type:	WELL	API Number:	045-10891	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	278572	Type:	WELL	API Number:	045-10890	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	278575	Type:	WELL	API Number:	045-10889	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	278577	Type:	WELL	API Number:	045-10888	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
				Material Handling And Spill Prevention	Pass	
		Ditches	Pass			
		Culverts	Pass			
Berms	Pass					
		Gravel	Pass			
		Compaction	Pass			
Check Dams	Pass					
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689700895	WF04B O23 596 photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4357464