

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/19/2018

Submitted Date:

01/19/2018

Document Number:

689700898

FIELD INSPECTION FORM

Loc ID 448472 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

Findings:
3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448452	WELL	XX	11/28/2016		045-23396	Puckett 24D-26-697	ND
448453	WELL	XX	11/28/2016		045-23397	Puckett 34B-26-697	ND
448454	WELL	DG	12/21/2017		045-23398	Puckett 12C-26-697	WO
448455	WELL	XX	11/28/2016		045-23399	Puckett 35B-26-697	ND
448456	WELL	XX	11/28/2016		045-23400	Puckett 24C-26-697	ND
448457	WELL	XX	11/28/2016		045-23401	Puckett 14B-26-697	ND
448458	WELL	XX	11/28/2016		045-23402	Puckett 33D-26-697	ND
448459	WELL	XX	11/28/2016		045-23403	Puckett 34A-26-697	ND
448460	WELL	DG	12/14/2017		045-23404	Puckett 12B-26-697	WO
448461	WELL	XX	11/28/2016		045-23405	Puckett 23A-26-697	ND
448462	WELL	XX	11/28/2016		045-23406	Puckett 14C-26-697	ND
448463	WELL	XX	11/28/2016		045-23407	Puckett 15A-26-697	ND
448464	WELL	XX	11/28/2016		045-23408	Puckett 13A-26-697	ND
448465	WELL	XX	11/28/2016		045-23409	Puckett 15B-26-697	ND
448466	WELL	XX	11/28/2016		045-23410	Puckett 11D-26-697	ND
448467	WELL	XX	11/28/2016		045-23411	Puckett 35A-26-697	ND
448468	WELL	XX	11/28/2016		045-23412	Puckett 34C-26-697	ND
448469	WELL	DG	01/05/2018		045-23413	Puckett 13B-26-697	WO
448470	WELL	XX	11/28/2016		045-23414	Puckett 14A-26-697	ND
448471	WELL	XX	11/28/2016		045-23415	Puckett 23C-26-697	ND
448473	WELL	DG	01/10/2018		045-23416	Puckett 13C-26-697	WO
448474	WELL	XX	11/28/2016		045-23417	Puckett 12A-26-697	ND
448475	WELL	DG	01/15/2018		045-23418	Puckett 13D-26-697	DG
448476	WELL	XX	11/28/2016		045-23419	Puckett 23B-26-697	ND

448477	WELL	XX	11/28/2016		045-23420	Puckett 23D-26-697	ND
448478	WELL	DG	12/27/2017		045-23421	Puckett 12D-26-697	WO
448479	WELL	XX	11/28/2016		045-23422	Puckett 24A-26-697	ND
448480	WELL	XX	11/28/2016		045-23423	Puckett 25B-26-697	ND
448481	WELL	XX	11/28/2016		045-23424	Puckett 34D-26-697	ND
448482	WELL	XX	11/28/2016		045-23425	Puckett 14D-26-697	ND
448483	WELL	XX	11/28/2016		045-23426	Puckett 24B-26-697	ND
448484	WELL	XX	11/28/2016		045-23427	Puckett 25A-26-697	ND

General Comment:

Location

Lease Road:

Type Access

comment:

Corrective Action:

Date:

Overall Good:

Signs/Marker:

Type DRILLING/RECOMP

Comment:

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type TRASH

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Location Construction

Location ID: 448475 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: Notices are being received.

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: <u>448452</u>	Type: <u>WELL</u>	API Number: <u>045-23396</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448453</u>	Type: <u>WELL</u>	API Number: <u>045-23397</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448454</u>	Type: <u>WELL</u>	API Number: <u>045-23398</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>448455</u>	Type: <u>WELL</u>	API Number: <u>045-23399</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448456</u>	Type: <u>WELL</u>	API Number: <u>045-23400</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448457</u>	Type: <u>WELL</u>	API Number: <u>045-23401</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448458</u>	Type: <u>WELL</u>	API Number: <u>045-23402</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448459</u>	Type: <u>WELL</u>	API Number: <u>045-23403</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448460</u>	Type: <u>WELL</u>	API Number: <u>045-23404</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>448461</u>	Type: <u>WELL</u>	API Number: <u>045-23405</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448462</u>	Type: <u>WELL</u>	API Number: <u>045-23406</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448463</u>	Type: <u>WELL</u>	API Number: <u>045-23407</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448464</u>	Type: <u>WELL</u>	API Number: <u>045-23408</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448465</u>	Type: <u>WELL</u>	API Number: <u>045-23409</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448466</u>	Type: <u>WELL</u>	API Number: <u>045-23410</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448467</u>	Type: <u>WELL</u>	API Number: <u>045-23411</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448468</u>	Type: <u>WELL</u>	API Number: <u>045-23412</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>448469</u>	Type: <u>WELL</u>	API Number: <u>045-23413</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>448470</u>	Type: <u>WELL</u>	API Number: <u>045-23414</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>

Facility ID: 448471 Type: WELL API Number: 045-23415 Status: XX Insp. Status: ND

Facility ID: 448473 Type: WELL API Number: 045-23416 Status: DG Insp. Status: WO

Facility ID: 448474 Type: WELL API Number: 045-23417 Status: XX Insp. Status: ND

Facility ID: 448475 Type: WELL API Number: 045-23418 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: H&P 330 Pusher/Rig Manager: Doug McAdam
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: 2500 Safety Plan: YES

Drill Fluids Management:

Lined Pit: Unlined Pit: Closed Loop: YES Semi-Closed Loop:
 Multi-Well: YES Disposal Location: Cuttings on northern edge of location.

Comment: 1/17/18 BOP test 250 psi low and 2500 psi high. Casing 1500 psi. Current depth 6857'

Corrective Action: Date:

Facility ID: 448476 Type: WELL API Number: 045-23419 Status: XX Insp. Status: ND

Facility ID: 448477 Type: WELL API Number: 045-23420 Status: XX Insp. Status: ND

Facility ID: 448478 Type: WELL API Number: 045-23421 Status: DG Insp. Status: WO

Facility ID: 448479 Type: WELL API Number: 045-23422 Status: XX Insp. Status: ND

Facility ID: 448480 Type: WELL API Number: 045-23423 Status: XX Insp. Status: ND

Facility ID: 448481 Type: WELL API Number: 045-23424 Status: XX Insp. Status: ND

Facility ID: 448482 Type: WELL API Number: 045-23425 Status: XX Insp. Status: ND

Facility ID: 448483 Type: WELL API Number: 045-23426 Status: XX Insp. Status: ND

Facility ID: 448484 Type: WELL API Number: 045-23427 Status: XX Insp. Status: ND

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
				Covering Materials	Pass	
Berms	Pass					
				Material Handling And Spill Prevention	Pass	
Compaction	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689700899	Drilling 13D-26-697 photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4357465