

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2018

Submitted Date:

01/16/2018

Document Number:

680302895**FIELD INSPECTION FORM**

Loc ID 426976	Inspector Name: SCHURE, KYM	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 3 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>200149</u> Name of Operator: <u>ATLAS RESOURCES LLC DBA ATLAS ROCKIES LLC</u> Address: <u>3500 MASSILLON ROAD #100</u> City: <u>UNIONTOWN</u> State: <u>OH</u> Zip: <u>44685</u>				

Contact Information:

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Walker, Chris	(817)439-4561	cwalker@atlasenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426960	WELL	PR	10/24/2012	GW	095-06387	MURRAY 943-34-31	SI

General Comment:

[Routine Site Inspection FIR](#)
[Contact: COGCC Engineering Supervisor \(Diana Burn\) for directives.](#)
[Enforcement Supervisor \(Jeremy Ferrin\) for directives.](#)
[Quality Assurance Supervisor \(Mike Leonard\) for directives.](#)

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:	Install sign to comply with Rule 210 series.	Date:	02/10/2018

Emergency Contact Number:

Comment:		
Corrective Action:	Install sign to comply with Rule 210 series.	Date: 02/10/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 426960 Type: WELL API Number: 095-06387 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well shows PR status. Well is SI/TA. Last production reporting June 2017.Corrective Action: Update well status. Update production reporting. Install valid signage.Date: 02/10/2018**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401516410	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4352827