

Final Reclamation and Stormwater Inspection

January 19, 2018

Operator: UNIOIL- 90950

API: 05-069-06196

Inspection Document #: 682403226

Larimer County, CO

NESW Section 25 T6N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MACLOUGHAN #25-1
API: 05-069-06196



Photo 1. Photo taken from the western location on September 19, 2017, facing East. Does not appear that any reclamation activities have been performed since the previous inspection.



Photo 2. Photo taken from the western location on January 19, 2018, facing East. Operator has performed final reclamation activities. Location has been temporarily stabilized with mulch.

Inspection Photos
Location Name: MACLOUGHAN #25-1
API: 05-069-06196



Photo 3. Photo taken from the southern location on January 19, 2018, facing North. See comment under Photo 2.



Photo 4. Photo taken from the access road south of the location on January 19, 2018, facing North. See comment under Photo 2.