

Inspection Photos

API: 05-067-06543

Operator: Holcomb Oil and Gas

Inspection Number: 680602434

Inspection Date: 1/9/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 3. View of the eastern portion of the project area from northeastern corner facing southward. Revegetation is progressing, largely with grasses such as smooth brome (*Bromus inermis*) and western wheatgrass (*Pascopyrum smithii*).