

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/23/2018

Submitted Date:

01/23/2018

Document Number:

688301101**FIELD INSPECTION FORM**Loc ID 449376 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: 600 N DAIRY ASHFORD RDCity: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Strickler, Robert		Robert.D.Strickler@conocophillips.com	<a href="#">All DJ Basin Inspections</a>
ConocoPhillips		COPColoradoReg@conocophillips.com	
Dixon, Jennifer	(701) 264-2041	jennifer.a.dixon@conocophillips.com	<a href="#">Regulatory Coordinator</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449378	WELL	DG	01/09/2018		001-10008	Aspen 3-65 15-14 2DH	DG

**General Comment:**[BOP Inspection](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:	signs at Hudson Rd, 56th Ave and Monaghan Rd		
Corrective Action:		Date:	
Type	OTHER		
Comment:	location sign at gate and location sign at entrance		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 855-595-8258

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 449378 Type: WELL API Number: 001-10008 Status: DG Insp. Status: DG**Well Drilling**

**Rig:** Rig Name: Nabors B16 Pusher/Rig Manager: Eric Witt  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: \_\_\_\_\_ Safety Plan: YES

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: 5000 psi high test, 250 psi low test

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688301106	ConocoPhillips Aspen 3-65 15-14 2DH BOP	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4359568">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4359568</a>