

# Inspection Photos

API: 05-067-07537

Operator: XTO ENERGY INC

Inspection Number: 680602444

Inspection Date: 1/9/2018



**Photo 1. View of project area from the southwestern corner facing center.**



**Photo 2. View of the southwestern portion of the project area from the southern corner facing northwestward.**



**Photo 3. View of the southern portion of the project area from the southeastern corner facing southwestward. Revegetation is progressing with grasses such as intermediate wheatgrass (*Thinopyron intermedium*) and smooth brome (*Bromus inermis*).**



**Photo 4. View of the northern portion of the project area from the northeastern corner facing southwestward. Surface owner trailers are stored along the western edge of the project area.**