

Inspection Photos

API: 05-067-07798

Operator: XTO ENERGY INC

Inspection Number: 680602452

Inspection Date: 1/9/2018



Photo 1. View of the project area from the northern corner facing center.



Photo 2. View of the northern portion of the project area from the northern corner facing southwestward.



Photo 3. View of the southern portion of the project area from the southeastern corner facing southwestward.



Photo 4. View of area in the western portion of the project area that appears to be eroding.