

Inspection Photos
Location Name: Dillard A #4-4
API: 05-123-24185



Photo 1: Location, looking SE



Photo 2: Wellhead, looking W

Inspection Photos
Location Name: Dillard A #4-4
API: 05-123-24185



Photo 3: Stained soil in separator house