

Final Reclamation Inspection

January 9, 2018

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Location ID: 327492 (well location and access road)

Inspection Document #: 682403192

Weld County, CO

NESE Section 7 T7N R59W

Chris Binschus
Reclamation Specialist, COGCC




COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ANDREWS #9-7
Location ID: 327492



Google Earth aerial imagery taken October 9, 1989 illustrating the access road was pre-existing prior to oil and gas operations.

Inspection Photos
Location Name: ANDREWS #9-7
Location ID: 327492



Aerial imagery from COGCC GISOnline database taken in 2015 illustrating the well location and battery location during operations. This is the most recent aerial imagery.

Inspection Photos
Location Name: ANDREWS #9-7
Location ID: 327492



Photo 1. Photo taken from the access road to the well location, facing South. Operator has failed to perform reclamation activities within 3-months of plugging the well on cropland. Access road with gravel remains in place.



Photo 2. Photo taken north of the well location, facing South. Well location with gravel remains in place.

Inspection Photos
Location Name: ANDREWS #9-7
Location ID: 327492



Photo 3. Photo taken from the well location, facing North. See comments under Photo 2.



Photo 4. Reference cropland photo taken north of the well location, facing West.