

Final Reclamation Inspection

January 9, 2018

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Location ID: 327492 (Tank battery location)

Inspection Document #: 682403219

Weld County, CO

NESE Section 7 T7N R59W

Chris Binschus
Reclamation Specialist, COGCC




COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Andrews Tank Battery
Location ID: 327492



Google Earth aerial imagery taken October 9, 1989 illustrating the access road was pre-existing prior to oil and gas operations.

Inspection Photos
Location Name: Andrews Tank Battery
Location ID: 327492



Aerial imagery from COGCC GISOnline database taken in 2015 illustrating the well location and battery location during operations. This is the most recent aerial imagery.

Inspection Photos
Location Name: Andrews Tank Battery
Location ID: 327492



Photo 1. Photo taken from the pit at the battery location, facing North. Operator has failed to backfill pit per Rule 1004. Operator has failed to comply with Rule 902.d.



Photo 2. Photo taken from the battery location, facing North. Operator has failed to remove equipment within 3-months of plugging the well.

Inspection Photos
Location Name: Andrews Tank Battery
Location ID: 327492



Photo 3. Photo taken from battery location, facing East. Operator has failed to remove unused equipment.



Photo 4. Photo taken from battery location, facing East. See comments under Photo 3.

Inspection Photos
Location Name: Andrews Tank Battery
Location ID: 327492



Photo 5. Photo taken from battery location, facing East.
See comments under Photo 3.



Photo 6. Photo taken from battery location, facing East.
See comments under Photo 3.