

Inspection Photos
Location Name: Kohlhoff #23-22
API: 05-123-23029



Photo 1: Location, looking S



Photo 2: Wellhead, looking N

Inspection Photos
Location Name: Kohlhoff #23-22
API: 05-123-23029



Photo 3: Stained soil at engine



Photo 4: Unused barrels at engine

Inspection Photos
Location Name: Kohlhoff #23-22
API: 05-123-23029



Photo 5: Unused hose in between separators



Photo 6: Stained soil at fence, N of engine