

Well Name : IGE 139

API # : 067-09534



Photo 1: Wellhead sign. Previous inspection.



Photo 2: Wellhead sign. Current inspection.

Well Name : IGE 139

API # : 067-09534



Photo 3: Frac sand pile. Previous inspection.



Photo 4: Cleaned up Frac sand pile. Current inspection.



Well Name : IGE 139

API # : 067-09534



Photo 5: Impacted soil. Previous inspection.



Photo 6: Impacted soil. Previous inspection.

Well Name : IGE 139

API # : 067-09534



Photo 7: Impacted soil. Previous inspection.



Photo 8: Impacted soil. Previous inspection.



Well Name : IGE 139

API # : 067-09534



Photo 9: Impacted soil. Current inspection.



Photo 10: Impacted soil. Current inspection.

Well Name : IGE 139

API # : 067-09534



Photo 11: Impacted soil. Current inspection.



Photo 12: Impacted soil. Current inspection.