

Inspection Photos
Location Holcomb Case #1-10
API: 05-067-06543



Northern access to location, looking south.



Trailer stored in SW corner of location.

Inspection Photos
Location Holcomb Case #1-10
API: 05-067-06543



View of southern (main) access road.



Open topped produced water vessel

Inspection Photos
Location Holcomb Case #1-10
API: 05-067-06543



Previously reclaimed area within “teardrop”.



Case #1-10 well head.