

| | | |
|------------------------------|---|---|
| FORM INSP Rev X/15 | State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109 | Inspection Date: <u>01/30/2018</u> Submitted Date: <u>01/30/2018</u> Document Number: <u>689700950</u> |
| FIELD INSPECTION FORM | | |



| | | |
|--|-------------------|---|
| Loc ID: <u>415372</u> Inspector Name: <u>LONGWORTH, MIKE</u> On-Site Inspection: <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED |
| Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u> | | Findings: 20 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested |

| | | | |
|-----------------------------|-------|---------------------------------------|---------------------------|
| Contact Information: | | | |
| Contact Name | Phone | Email | Comment |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Leonard, Mike | | mike.leonard@state.co.us | |
| , Caerus Piceance | | COGCC.inspections@caerusoilandgas.com | Piceance inspections only |

| Inspected Facilities: | | | | | | | |
|------------------------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
| 415326 | WELL | PR | 01/05/2012 | GW | 045-19024 | N. PARACHUTE WF06A-26H26596 | PR |
| 415331 | WELL | PR | 02/22/2012 | GW | 045-19027 | N. PARACHUTE WF14B-26H26596 | PR |
| 415333 | WELL | PR | 01/05/2012 | GW | 045-19028 | N. PARACHUTE WF04A-35H26596 | PR |
| 415339 | WELL | PR | 11/25/2011 | GW | 045-19031 | N. PARACHUTE WF03A-25H26596 | PR |
| 415340 | WELL | PR | 01/08/2012 | GW | 045-19032 | N PARACHUTE WF13C-26H26596 | PR |
| 415345 | WELL | PR | 01/05/2012 | GW | 045-19035 | N. Parachute WF13C-24H26 59 | PR |
| 415350 | WELL | PR | 02/22/2012 | GW | 045-19036 | N. Parachute WF05C-26H26 59 | PR |
| 415356 | WELL | PR | 01/02/2012 | GW | 045-19039 | N. Parachute WF05B-26H26 59 | PR |
| 415357 | WELL | PR | 02/07/2012 | GW | 045-19040 | N. Parachute WF04B-25H26 59 | PR |
| 415362 | WELL | PR | 01/05/2012 | GW | 045-19042 | N. PARACHUTE WF03B-35H26596 | PR |
| 415363 | WELL | PR | 02/22/2012 | GW | 045-19043 | N. Parachute WF06D-26H26 59 | PR |
| 415373 | WELL | PR | 12/05/2011 | GW | 045-19045 | N. PARACHUTE WF14B-24H26596 | PR |
| 415378 | WELL | PR | 02/07/2012 | GW | 045-19047 | N. PARACHUTE WF04C-25H26596 | PR |
| 415379 | WELL | PR | 03/09/2012 | GW | 045-19048 | N. PARACHUTE WF12B-26H26596 | PR |
| 415382 | WELL | PR | 03/09/2012 | GW | 045-19049 | N. Parachute WF12A-26H26 59 | PR |

| | | | | | | | |
|--------|------|----|------------|----|-----------|-----------------------------|----|
| 415387 | WELL | PR | 01/08/2012 | GW | 045-19050 | N. PARACHUTE WF12C-26H26596 | PR |
|--------|------|----|------------|----|-----------|-----------------------------|----|

General Comment:

| Location | | | |
|--|---|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action: | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | Battery sign is missing emergency contact number. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | | Date: 02/02/2018 |
| Good Housekeeping: | | | |
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Equipment: | | | |
| Type: Gas Meter Run | # 16 | | corrective date |
| Comment: | Gas lift | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 16 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 16 | | |
| Comment: | Sells | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 415326 | Type: | WELL | API Number: | 045-19024 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 415331 | Type: | WELL | API Number: | 045-19027 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 415333 | Type: | WELL | API Number: | 045-19028 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 415339 | Type: | WELL | API Number: | 045-19031 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 415340 | Type: | WELL | API Number: | 045-19032 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 415345 | Type: | WELL | API Number: | 045-19035 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 415350 | Type: | WELL | API Number: | 045-19036 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 415356 | Type: | WELL | API Number: | 045-19039 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |

| | | | | |
|-------------------------|------------|-----------------------|------------|------------------|
| Facility ID: 415357 | Type: WELL | API Number: 045-19040 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 415362 | Type: WELL | API Number: 045-19042 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 415363 | Type: WELL | API Number: 045-19043 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 415373 | Type: WELL | API Number: 045-19045 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 415378 | Type: WELL | API Number: 045-19047 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 415379 | Type: WELL | API Number: 045-19048 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 415382 | Type: WELL | API Number: 045-19049 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 415387 | Type: WELL | API Number: 045-19050 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | Culverts | Pass | | | |
| Ditches | Pass | | | | | |
| Compaction | Pass | | | | | |
| | | | | Material Handling And Spill Prevention | Pass | |
| | | Ditches | Pass | | | |
| Berms | Pass | | | | | |
| | | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 689700952 | Location H26 Battery sign missing emergency number | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4365151 |