

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2018

Submitted Date:

01/30/2018

Document Number:

679903909

**FIELD INSPECTION FORM**

Loc ID 321874 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10634  
Name of Operator: P O & G OPERATING LLC  
Address: 5847 SAN FELIPE SUITE 3200  
City: HOUSTON State: TX Zip: 77057

**Findings:**

- 13 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Chatfield, Tommy	(713) 589-8186	tommy_chatfield@pogresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208293	WELL	PR	07/27/1991	OW	017-07228	ROUT 2	PR

**General Comment:**

[Routine Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Lease sign at tank battery. Update to current operator		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit. Update to current operator		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks. Add labeling to water tank		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>		
Comment:	<input style="width: 500px;" type="text"/>	
Corrective Action:	<input style="width: 500px;" type="text"/>	Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type:	Ancillary equipment # 5		
Comment:	Gas scrubber, 2-propane tanks, cathodic generator and rectifier		
Corrective Action:		Date:	
Type:	Vertical Heater Treater # 1		
Comment:	Treater with metal shed		
Corrective Action:		Date:	
Type:	Prime Mover # 1		
Comment:	Arrow gas engine		
Corrective Action:		Date:	
Type:	Pump Jack # 1		
Comment:	Lufkin 160		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		38.824580,-102.640370
Comment: <a href="#">Water tank on north side of oil tanks</a>					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <a href="#">Shared berms</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		38.824580,-102.640370
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 208293 Type: WELL API Number: 017-07228 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT