

# Interim Reclamation Inspection

January 30, 2018

Operator: BAYSWATER EXPLORATION & PRODUCTION LLC- #10261

Location ID: 433400

Inspection Document #: 682403243

Weld County, CO

NWSW Section 18 T7N R66W

Chris Binschus  
Reclamation Specialist, COGCC




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Vair /18I-Pad  
Location ID: 433400



Aerial imagery taken June 19, 2014 post drilling operations of the Vair /18I-Pad. Red-line indicates disturbance area.



Aerial imagery taken October 14, 2017 post drilling operations of the Vair /18I-Pad. Portions of the northern and western interim do not meet Rule 1003 standards, as weedy, annual vegetation (Kochia) dominates the area. It appears portions of the northeastern and eastern interim areas would meet Rule 1003 standards- see the following photos for more detail.

Inspection Photos  
Location Name: Vair /18I-Pad  
Location ID: 433400



**Photo 1.** Photo taken from the western interim area, facing North. This area does not meet Rule 1003 standards, as weedy, annual vegetation (Kochia) dominates the area which is not reflective of reference area vegetative levels.



**Photo 2.** Reference photo taken just west of the western interim area, facing West. Reference area vegetation consist mostly of Crested wheatgrass (*Agropyron cristatum*) and Rabbitbrush.

Inspection Photos  
Location Name: Vair /18I-Pad  
Location ID: 433400



**Photo 3.** Photo taken from the northwestern interim area, facing East. See comments under Photo 1.



**Photo 4.** Photo taken from the eastern interim area, facing South. This area appears to meet Rule 1003 standards. Rabbitbrush appears to be at a higher density than Crested wheatgrass but Kochia did not appear to have a significant establishment.

Inspection Photos  
Location Name: Vair /18I-Pad  
Location ID: 433400



**Photo 5.** Photo taken of the tank battery sign at location. PDC has just acquired this location on January 8, 2018.



**Photo 6.** Photo taken of the well head sign at location. The previous Operator sign is not reflective of the current Operator. PDC shall comply with Rule 210.b.