

Burlington Resources Oil & Gas LP, B&D Land 4-64 4-5 4BH
005-07245

Inspection #688301112

1/26/2018

Routine/New Equipment Inspection

ConocoPhillips



B&D LAND 4-64 4-5 4BH

01.26.2018



ConocoPhillips

**BURLINGTON RESOURCES
B&D LAND 4-64 4-5 4BH**

SE/SE SEC. 4 TWP. 4S R. 64W

ARAPAHOE COUNTY, CO. ELEVATION 5617.1'

ACCESS LOCATION FROM MANILA RD. & EAST 6TH AVE.

24 HR. CONOCO PHILLIPS CONTACT: 1-855-355-8258

LOCAL EMERGENCY SERVICES: 911 NO SMOKING

01.26.2018



01.26.2018

ConocoPhillips

BURLINGTON RESOURCE

B&D LAND 4-64 4-5 4E

SE/SE SEC. 4 TWP: 4S RNG: 64W

24 HR. CONOCO PHILLIPS CONTACT: 1-855-595-8258

LOCAL EMERGENCY SERVICES: 911

NO SMOKING

01.26.2018

SE/SE SEC. 4 TWP: 4S RNG: 64W
APAHOE COUNTY, CO. ELEVATION 561
S LOCATION FROM MANILA RD. & EAST
R. CONOCO PHILLIPS CONTACT: 1-855-595-
EMERGENCY SERVICES: 911 NO S

01.26.2018









01.26.2018



01.26.2018



Valve leak
at treater,
contacted
operator on
1/26/2018
who said
someone
would be
sent out
right away.



01.26.



01.26.2018

AIRS ID# 005-1632-007

01.26.





01.26.2018



01.26.2018





01.26.2018



01.26.2018



01.26.2018



01.26.2018