

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 9:44:27 AM
37.12919N 104.64001W

Purgatorie River at County Road 18.3 - Upstream



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Purgatorie River at County Road 18.3 - Downstream



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 9:57:11 AM
37.12347N 104.70853W

Purgatorie River at County Road 47.7 - Upstream



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 9:57:37 AM
37.12360N 104.70845W

Purgatorie River at County Road 47.7 - Downstream



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:06:46 AM
37.12162N 104.77623W

Purgatorie River at Hill Ranch Road - Downstream



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:06:59 AM
37.12161N 104.77629W

Purgatorie River at Hill Ranch Road - Upstream



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Purgatorie River near County Road 18.6 - Upstream



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:15:47 AM
37.13244N 104.83107W

Purgatorie River near County Road 18.6 - Downstream



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:21:31 AM
37.13175N 104.84691W

Purgatorie River at County Road 31.9 – Upstream. COGCC Sample Site #4



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Purgatorie River at County Road 31.9 – Upstream.



Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:24:42 AM
37.13203N 104.84727W

Wet Canyon just upstream from Purgatorie River. COGCC Sample Site #2.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:26:27 AM
37.13228N 104.84728W

Wet Canyon just upstream from Purgatorie River. 4 square foot oil sheen observed upstream of boom.



Location Name: Spill 453631

Inspection Date: 1/31/18



Wet Canyon just upstream from Purgatorie River. COGCC Sample Site #1. Hydrocarbon foam and 2 square foot sheen observed above boom.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:32:50 AM
37.13938N 104.85488W

Wet Canyon



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Wet Canyon. No seen observed upstream of boom.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:34:27 AM
37.13946N 104.85506W

Wet Canyon



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:37:57 AM
37.13292N 104.85075W

Wet Canyon



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:39:09 AM
37.14591N 104.85969W

Wet Canyon



Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:40:43 AM
37.14647N 104.86037W

Wet Canyon. COGCC Sample Site #3. Looking Upstream



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:41:00 AM
37.14642N 104.86035W

Wet Canyon. COGCC Sample Site #3. Looking Upstream



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:44:32 AM
37.14752N 104.86135W

Wet Canyon



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Thin oil sheen in Wet Canyon. Approximately 5 square feet. Difficult to see in picture.



Location Name: Spill 453631

Inspection Date: 1/31/18



Wet Canyon just downstream below dry drainage where spill occurred (see next photo). Small sheen observed here. Stream is 2 feet wide.

Location Name: Spill 453631

Inspection Date: 1/31/18



Wet Canyon just downstream below dry drainage where spill occurred. Spill flowed through culvert pictured. Small sheen observed here. Same sheen shown in previous photo.



Location Name: Spill 453631

Inspection Date: 1/31/18



Dry drainage where spill occurred. No live water observed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Spill 453631

Inspection Date: 1/31/18



Jan 31, 2018 10:53:43 AM
37.14877N 104.86043W

Dry drainage where spill occurred. No live water observed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources