

Inspection Photos
Location Name: Shaw E Unit 1
API: 05-001-09193



Wellhead **Corrective Action: Unused equipment at wellhead, comply with 603.f**



Battery **Corrective Action: Unused Enardo valve and piping on top of water tank. Comply with 603.f**

Inspection Photos
Location Name: Shaw E Unit 1
API: 05-001-09193



Separator