


Becca Oil LLC, Kalcevic 2
005-06449

Inspection #688301124

1/30/2018

Routine Inspection

A photograph of an oil well valve in a dry, open field. The valve is a horizontal pipe with a vertical riser on the right side. A white identification tag is attached to the horizontal pipe. The tag contains the following text: "BECCA OIL L.L.C", "KALCEVIC #2", "SWNW SEC12-T4S R63W", "ARAPAHOE COUNTY, CO", and "EMERGENCY NO. 303-881-2482 918-225-2334 OR 911". The date "01.30.2018" is printed in orange in the bottom right corner of the image.

BECCA OIL L.L.C

KALCEVIC #2
SWNW SEC12-T4S R63W
ARAPAHOE COUNTY, CO

EMERGENCY NO. 303-881-2482 918-225-2334
OR 911

01.30.2018



01.30.2018



BECCA OIL L.L.C.
KALCEVIC #2
SW1/4 SEC12-T4S R63W
ARAPAHOE COUNTY, CO
EMERGENCY NO. 303-225-2042 303-225-2034
OR 911

01.30.2018



01.30.2018