

- Cundiff Federal B 1
- 05-067-07174



Photo 1: Wellhead sign. Previous inspection.

- Cundiff Federal B 1
- 05-067-07174



Photo 2: Wellhead sign. Current inspection.

- Cundiff Federal B 1
- 05-067-07174



Photo 3: Gravel and soil pile. Previous inspection.

- Cundiff Federal B 1
- 05-067-07174



Photo 4: Cleaned-up/removed soil and gravel pile.

- Cundiff Federal B 1
- 05-067-07174



Photo 5: Erosion rilling with sediment flow onto location in NE corner. Previous inspection.

- Cundiff Federal B 1
- 05-067-07174



Photo 6: Repaired cut slope.

- Cundiff Federal B 1
- 05-067-07174



Photo 7: Erosion with sediment flow onto location in NE corner. Previous inspection.

- Cundiff Federal B 1
- 05-067-07174



Photo 8: Repaired cut slope and new ditch and berm.

- Cundiff Federal B 1
- 05-067-07174



Photo 9: Backhoe bucket and wood on perimeter. Previous inspection. Previous inspection.

- Cundiff Federal B 1
- 05-067-07174



Photo 10: Backhoe bucket and wood removed from perimeter.

- Cundiff Federal B 1
- 05-067-07174



**Photo 11: Rail road tie and concrete block on perimeter.
Previous inspection.**

- Cundiff Federal B 1
- 05-067-07174



**Photo 12: Rail road tie and concrete block removed from
perimeter.**

- Cundiff Federal B 1
- 05-067-07174



Photo 13: Disconnected piping on perimeter. Previous inspection.

- Cundiff Federal B 1
- 05-067-07174



Photo 14: Pipe removed from perimeter.

- Cundiff Federal B 1
- 05-067-07174



Photo 15: Wire rope coming out of the ground outside of wellhead fencing. Previous inspection.

- Cundiff Federal B 1
- 05-067-07174



Photo 16: Wire rope removed.

- Cundiff Federal B 1
- 05-067-07174



Photo 17: New ditch and berm at base of cut slope.

- Cundiff Federal B 1
- 05-067-07174



Photo 18: New berm along perimeter of location.