

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/31/2018

Submitted Date:

02/06/2018

Document Number:

678301447

FIELD INSPECTION FORM

Loc ID 318540 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453909	TANK BATTERY	AC	01/31/2018		-	Brown 1 battery	EI

General Comment:

[battery not co-located with well and well not inspected at this time](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	earthen berm		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV CONCRETE		,
Comment:	<input type="text"/>				

Corrective Action:	Date:
--------------------	-------

Paint

Condition		
Other (Content)		
Other (Capacity)	75 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient		Adequate
Comment: bern shared with crude tank				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 453909 Type: TANK API Number: - Status: AC Insp. Status: EI