

Photo#1:

Two piles of unused, unneeded Pipe are stored on West & South side of Location.



Photo#2:



January 19, 2018



Photo#3:  
Access Road Leading into Location.



Photo#4:  
Sediment Trap off East Side of Access Road.



January 19, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc#334790



Photo#5:

Sections of Location Fill Slopes are incorporated into Cut Slope of Large Location located below.



January 19, 2018