

Well Name : Bullseye 22

API # : 067-09814



Photo 1: Wellhead sign.



Photo 2: 95 BBL open top tank with below grade labels.

Well Name : Bullseye 22

API # : 067-09814



Photo 3: NFPA label on tank battery fencing does not match any labels on tanks.



Photo 4: Risers at wellhead for unused 2" and 1" lines.



Well Name : Bullseye 22

API # : 067-09814



Photo 5: 2" flowline connected at separator.



Photo 6: 1" flowline connected at separator.



Well Name : Bullseye 22

API # : 067-09814



Photo 7: Breach in berm in NE corner with erosion channel in background.



Photo 8: Breach in berm and undercut straw waddle.



Well Name : Bullseye 22

API # : 067-09814



Photo 9: Erosion channel on fill slope.



Photo 10: Cut slope slide area behind tank battery.

Well Name : Bullseye 22

API # : 067-09814



Photo 11: Base of slide at tank battery.



Photo 12: Unstable soil on cut slope.



Well Name : Bullseye 22

API # : 067-09814



Photo 11: Wider view of cut slope.



Photo 12: Slide pushing into tank battery fencing.