

# Inspection Photos

02/05/2018

Operator: VISTA OPERATING INC - 100128

Location ID: 317407

Inspection Doc. Number: 682503116

Washington County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: VISTA OPERATING INC - 100128  
Location ID: 317407



**Photo 1:** Photo taken from the west end of the location, facing east. Photo shows location remains predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted.



**Photo 2:** taken from the west end of the location, facing north. Photo shows location remains predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted.

Inspection Photos  
Operator: VISTA OPERATING INC - 100128  
Location ID: 317407



**Photo 3:** taken from the south end of the location, facing north. Photo shows location remains predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted.



**Photo 4:** Photo taken the north end of the location. Photo shows location remains predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted.

Inspection Photos  
Operator: VISTA OPERATING INC - 100128  
Location ID: 317407



**Photo 5:** Photo taken from the north end of the location, facing north. Photo shows erosion degradation cutting up hill from location.



**Photo 6:** Photo taken from the adjacent reference area. Photo shows vegetation to be compared to the disturbance. Vegetation seen is predominantly prairie sandreed, blue grama, buffalo grass, sand dropseed, yucca, etc...