

Inspection Photos

02/05/2018

Operator: VISTA OPERATING INC - 100128

Location ID: 317408

Inspection Doc. Number: 682503118

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: VISTA OPERATING INC - 100128
Location ID: 317408



Photo 1: Photo taken from the south end of the location, facing north. Photo shows location remains predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted.



Photo 2: Photo taken from the well location. Photo shows vegetation over the well area. Vegetation seen here predominantly an annual aster species. Location predominantly bare and expose soil.

Inspection Photos
Operator: VISTA OPERATING INC - 100128
Location ID: 317408



Photo 3: Photo taken from the location, facing north. Photo shows vegetation over the reclamation area. Vegetation seen here predominantly an annual aster species. Location predominantly bare and expose soil.



Photo 4: Photo taken from the north end of the location. Photo shows vegetation. Vegetation seen here predominantly an annual aster species. Location predominantly bare and expose soil. Unable to find evidence that additional reclamation has been conducted

Inspection Photos
Operator: VISTA OPERATING INC - 100128
Location ID: 317408



Photo 5: Photo taken north end of the location at the access road. Photo shows metal stake on the west side of the access road.



Photo 6: Photo taken north end of the location at the access road. Photo shows metal stake on the east side of the access road.

Inspection Photos
Operator: VISTA OPERATING INC - 100128
Location ID: 317408



Photo 7: Photo taken from the north end of the location, facing east. Photo shows access road has not been adequately reclaimed.



Photo 8: Photo taken access road northeast of the location at coordinates 39.83686/-102.85993. Photo shows pipe riser that has not been removed.



Photo 9: Photo taken from the adjacent reference area. Photo shows vegetation to be compared to the disturbance. Vegetation seen is predominantly prairie sandreed, blue grama, buffalo grass, sand dropseed, yucca, etc...