

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/07/2018

Submitted Date:

02/08/2018

Document Number:

678301515**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 328712 GINTAUTAS, PETER 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

General Comment:

visual inspection of area where battery facility had been located. SE corner of berm at 40.279086, -104.812377. REM 10977 submitted for removal of PBV PW tank. only equipment left on site of battery is GMR connecting to DCP line. Data submitted with REM 10977 indicate no impacts to soils or groundwater from PBV