

Photo#1:
Overview of Location to West.



January 30, 2018

Photo#2:

Two views of Unused Equipment on Location

Photo#3:



January 30, 2018

Photo#4:

Several Tamarisk Plants (B List Noxious Weed) & Cocklebur were noted in water retainment areas of Location.

Photo#5:



January 30, 2018

Photo#6:

Areas of Access Road, down gradient from Location needs Maintenance



January 30, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Shwartz Loc#334740